

FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management Solid Waste Section

UNIT TYPE:												
Lined MSWLF	L	CID		YW		Transfer		Compost		SLAS	X	COUNTY: Robeson
Closed MSWLF	H	łW		White goods		Incin		T&P		FIRM		PERMIT NO.: SLAS 78-18
CDLF		Γ&P / ection		Tire Monofill		Industrial Landfill		DEMO		SDTF		FILE TYPE: COMPLIANCE

Date of Site Inspection: 3/28/2013 **Date of Last Inspection:** 10/12/2012

FACILITY NAME AND ADDRESS:

Marshall Cummings Septic Tank Service 1234 W. McDuffie Crossing Road St. Pauls, NC 28384

GPS COORDINATES: N: 34.82310 W: -79.04520

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Marshall Cummings Telephone: (910) 737-6310

Email address: lmc9650@earthlink.net

Fax: N/A

FACILITY CONTACT ADDRESS:

N/A

PARTICIPANTS:

Connie Wylie

STATUS OF PERMIT:

Active

PURPOSE OF SITE VISIT:

Routine

STATUS OF PAST NOTED VIOLATIONS:

N/A

OBSERVED VIOLATIONS

1. N/A

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

SEE BACK

FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

- 1. The winter cover crop appears somewhat patchy. Contact Rick Morris for advice concerning weed control or reseeding during the spring months.
- 2. The field markers are adequate and it appears that the approved setbacks are being met.
- 3. The required signs are posted and the access road is adequate.
- 4. No recent application and no odors noted.
- 5. Ensure that the 50' buffer is maintained from the front of the disposal fields to any neighboring crop for human consumption.

Please contact me if you have any questions or concerns regarding this inspection report.

Connie S. Wylie

Can S. Wyle

Regional Representative

Sent on:	Email	Hand delivery	X	US Mail	Certified No. [_]

Phone: (910) 433-3352